

May 18, 2011

TO: Darlene Evans, STB, Fax 245-0464

229534

FROM: John D. Heffner

RE: discrepancy of mileposts in FD 35500

Darlene, the reason for the discrepancy in the distance of the operating rights for interchange purposes (MP 39.44 to MP 35.0, 3.2 miles) is that the point identified as MP 35 used to have a different milepost identification. During the course of time D&H Railway made changes to the track or right of way with the result that the distance was shortened and/or the milepost at the point of interchange was changed. This information comes from CP attorney Karl Hansen.

John Heffner

ENTERED  
Office of Proceedings  
MAY 19 2011  
Part of  
Public Record